

JOHN A. WILSON,  
Civil Engineer.

JOS. M. WILSON,  
Civil Engineer & Arch<sup>t</sup>

FRED. G. THORN,  
Architect.

HENRY W. WILSON,  
Civil Engineer.

CHARLES G. DARRACH,  
Civil & Hydraulic Engineer.

HENRY A. MACOMB,  
Architect.

# Wilson Brothers & Co.

## Civil Engineers and Architects.

No. 435 Chestnut St.  
Philadelphia, Pa.

May 5th, 1887.

Hon. Daniel M. Fox, Supt.,

United States Mint,

Philadelphia.

Dear Sir:

Enclosed please find Estimate No. 1, for work done by Charles McCaul under his contract for new boiler room, &c., &c.

You will notice item as follows: "Brick Underpinning at \$13.50 per cubic yard." There is no item in the contract for brick underpinning; but the contract provides for the engineers and architects allowing a just and equitable price for such work, the price of which is not specifically mentioned.

In the excavation of the old foundations of the Mint, it was discovered that it was so poor, <sup>that</sup> it was absolutely unsafe to excavate sufficient <sup>wall</sup> to underpin with stone. We therefore, were obliged to substitute brick underpinning; and the price, (\$13.50) bears precisely the same relation to stone underpinning, as stone wall would to brick wall. We make this explanation so that you may understand how the price was arrived at.

Respectfully yours,

*Wilson Bros & Co.*

2 ENCLOSURE

Wilson Brothers & Co.  
Civil Engineers and Architects,  
Philadelphia, Pa.,  
May 5, 1887

Hon. Daniel M. Fox, Supt.,  
United States Mint,  
Philadelphia.

Dear Sir:

Enclosed please find Estimate No. 1, for work done by Charles McCaul under his contract for new boiler room, &c., &c.

You will notice item as follows: "Brick Underpinning at \$13.50 per cubic yard." There is no item in the contract for brick underpinning; but the contract provides for the engineers and architects allowing a just and equitable price for such work, the price of which is not specifically mentioned.

In the excavation of the old foundations of the Mint, it was discovered that it was so poor that it was absolutely unsafe to excavate sufficient wall to underpin with stone. We therefore, were obliged to substitute brick underpinning; and the price, (\$13.50) bears precisely the same relation to stone underpinning, as stone wall would to brick wall. We make this explanation so that you may understand how the price was arrived at.

Respectfully yours,  
Wilson Bro. & Co.  
D.

2 ENCLOSURES